

Talk No. 29

Start time	End

EELS / MACHINES

Duration

Ilt in accidents, often because the

1. Introduction:

1.1 Misuse of abrasive wrong type of whee

2. Main Points:

- 2.1 Wheels must only e
- 2.2 Machine speeds mu wheel.
- 2.3 Eye and ear protect

a competent person.

kimum permissible speed of the

rn.

3. Points to remember

- 3.1 Don't exert heavy p
- 3.2 Don't use the sides
- 3.3 Keep fingers clear d
- 3.4 Ensure any guards surface required for
- 3.5 Be aware of other w
- 3.6 Adjust tool rests to
- 3.7 Only reinforced disc
- 3.8 Run replacement w stand well clear.
- 3.9 Always stop wheels
- 3.10 Keep the face of the
- 3.11 Visually check whee verification.

b.

and used — the minimum wheel sed.

not expose them to risk.


the face of the wheel.

d-held machines.

or to using them, ensuring you

vious faults — if in any doubt get

1



SHEE

	7111214		<u> </u>	
Talk No. 29	Ĺ		EELS / MACHINES	
All operatives listed a			Box Talk.	
NAME				
		Λ		
		IVI		